

# Facts

---

## Product information

Dry extinguishing

XC1001-A new firmware

**September 5, 2007**  
Gerald Codourey, 2381  
SBT International

**92, Fire Protection**  
Product information  
No. 92E008-I

**Product, (ASN):**  
**XC1001-A**

**Target audience:**  
Regional Companies  
Representative Offices  
Sales Managers  
SBT INT Partners  
Internally SBT INT



---

# Contents

1. Contents.....	3
New firmware v 2.7 .....	3
Technical manual updated .....	3

Yours faithfully,

Siemens Switzerland Ltd.  
SBT International

Sign. Rüdiger Hildebrand  
Head Marketing & Technical Support

Sign. Gerald Codourey  
Product Manager Fire Safety

**SIEMENS****Building Technologies**

Fire Safety &amp; Security Products

Product Information

Product Line: Fire Detection

Distribution (please mark):

Product Solution Multi-channel 

Product family:	Product name:	Order-No:
XC10	XC 1001-A	A6E60500060

## New Firmware v2.7 for XC1001-A Technical Manual for XC1001-A updated

**For XC1001-A, we have released a new firmware version v2.7**

**The Technical Manuals for XC1001-A were updated.**

### Changes in Firmware v2.7:

Additional functions:

- Driver output 1 : new option selection for process as a "Fire control" or not
- Control line 5 : new option selection for process as a "Horn"
- Control line 5 : new option selection for process as a "Manual only" or "Automatic & manual blocked" output
- Contact 1 "RT Alarm" : new option selection for activation or not in case Z3 and Z4
- Control line 2 : new option selection for process as a "Manual only" or "Automatic & Manual blocked" warning panel
- New option selection for de-activation of warning panel with one digit code
- Contact 3 : new option selection for "Hold/Abort" output indication
- Driver output 2 : new option selection for process as a "Fail safe magnetic door contact"
- Control line 1 : new options selection for additional horn pulsating frequency
- Zone 3 : new option selection to connect an air sampling system
- Driver output 8 : new option selection to provide additional information's to a DMS

7 country pre-settings are implemented

Some minor bug fixing

<b>Author:</b> Gerald Codourey <b>SIEMENS</b> Switzerland Ltd. SBT International Gubelstrasse 22 CH-6301 Zug	Page: 3	<b>PLN number:</b> FD_07_015_PI_XC10- Firmware-v2-70_en  92E008-I - September 5, 2007
--	---------	--

**Product Line:** Fire Detection

**Distribution (please mark):**


Product  Solution  Multi-channel

Information's:

- An update of existing installation is **not required**
- The new SW 2.7 will be implemented on stock approximately from mid of June
- The technical manual will be available on STEPS from beginning of June
- How to identify new SW version :
  - on the main board :



- on the product label :



**Additional information**

If you need additional information, please contact SBT INT Marketing & Technical Support.

**Customer Support:**

E-mail: gerald.codourey@siemens.com

Phone: +41 41 724 2381

Fax: +41 41 724 2369

<https://www.siemens.com/buildingtechnologies-Login/>

<p><b>Author:</b> Gerald Codourey  <b>SIEMENS</b> Switzerland Ltd.                  SBT International                  Gubelstrasse 22                  CH-6301 Zug</p>	<p>Page: 4</p>	<p><b>PLN number:</b> FD_07_015_PI_XC10-                  Firmware-v2-70_en                  92E008-I - September 5, 2007</p>
---	----------------	---